ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
51323414	13
DATE 8·21·2020	

MOTOR CARRIER OPERATOR: Roy Salmon Trucking LLC	INSPECTOR'S NAME (PRINT OR TYPE): FRANS RUSSEL FRANSIS
ADDRESS: 8333 Pulaski Hwy	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES
CITY, STATE, ZIP CODE: Rosedale MD 21237	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER: 1FUJGLDSXEDFU2568
VEHICLE TYPE ☑ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
✓			f. Low Pressure Warning Device
✓			g. Tractor Protection Valve
✓			h. Air Compressor
NA			i. Electric Brakes
NA			j. Hydraulic Brakes
NA			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
			2. COUPLING DEVICES
✓			a. Fifth Wheels
✓			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
✓			d. Drawbar/Towbar Tongue
✓			e. Safety Devices
✓			f. Saddle-Mounts
			3. EXHAUST SYSTEM
✓			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.
✓			b. Bus exhaust system leaking or discharging in violation of standard.
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.
			4. FUEL SYSTEM
✓			a. Visible leak.
✓			b. Fuel tank filler cap missing.
✓			c. Fuel tank securely attached.
			5. LIGHTING DEVICES
✓			All lighting devices and reflectors required by Part 393 shall be operable.
			6. SAFE LOADING
✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
✓			b. Protection against shifting cargo.
✓			c. Container securement devices on intermodal equipment.
			7. STEERING MECHANISM
✓			a. Steering Wheel Free Play
✓			b. Steering Column
✓			c. Front Axle Beam and All Steering Components Other Than Steering Column
✓			d. Steering Gear Box
✓			e. Pitman Arm
✓			f. Power Steering
✓			g. Ball and Socket Joints
✓			h. Tie Rods and Drag Links
✓			i. Nuts
✓			j. Steering System
			8. SUSPENSION
✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
			9. FRAME
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			10. TIRES
✓			a. Tires on any steering axle of a power unit.
✓			b. All other tires.
✓			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
			11. WHEELS AND RIMS
✓			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds
			12. WINDSHIELD GLAZING
✓			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
			13. WINDSHIELD WIPERS
✓			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			14. MOTORCOACH SEATS
✓			Any passenger seat that is not securely fastened to the vehicle structure.
			15. OTHER
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION ACCORDANCE WITH 49 CFR PART 396.

Copyright 2016 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868

ORIGINAL