

# ANNUAL VEHICLE INSPECTION REPORT

## VEHICLE HISTORY RECORD

REPORT  
NUMBER

FLEET UNIT NUMBER

DATE **5-1-19**

MOTOR CARRIER OPERATOR

**ROY SALMON TRUCKING LLC**

ADDRESS  
**P.O. Box 799**

CITY, STATE, ZIP CODE

**RANDALLSTOWN, 21133**

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS

☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

**RODNEY FARMER**

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

**3H3V532CX9T703007**

INSPECTION AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKE SYSTEM</b>				<b>6. SAFE LOADING</b>				<b>10. TIRES</b>
✓			a. Service Brakes	✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	✓			a. Tires on any steering axle of a power unit.
✓			b. Parking Brake System				b. Protection against shifting cargo.	✓			b. All other tires.
✓			c. Brake Drums or Rotors				c. Container securement devices on intermodal equipment.	✓			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
✓			d. Brake Hose								
✓			e. Brake Tubing								
NA			f. Low Pressure Warning Device	✓							
NA			g. Tractor Protection Valve	✓							
NA			h. Air Compressor								
NA			i. Electric Brakes								
NA			j. Hydraulic Brakes								
NA			k. Vacuum Systems								
✓			l. Antilock Brake System	NA							
✓			m. Automatic Brake Adjusters								
			<b>2. COUPLING DEVICES</b>				<b>7. STEERING MECHANISM</b>				<b>11. WHEELS AND RIMS</b>
NA			a. Fifth Wheels				a. Steering Wheel Free Play	✓			a. Lock or Side Ring
			b. Pintle Hooks				b. Steering Column	✓			b. Wheels and Rims
			c. Drawbar/Towbar Eye				c. Front Axle Beam and All Steering Components Other Than Steering Column	✓			c. Fasteners
			d. Drawbar/Towbar Tongue				d. Steering Gear Box	✓			d. Welds
			e. Safety Devices				e. Pitman Arm				
NA			f. Saddle-Mounts				f. Power Steering	NA			
			<b>3. EXHAUST SYSTEM</b>				<b>8. SUSPENSION</b>				<b>12. WINDSHIELD GLAZING</b>
NA			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	NA			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
			b. Bus exhaust system leaking or discharging in violation of standard.	✓			b. Spring Assembly				
			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓			c. Torque, Radius or Tracking Components				
			<b>4. FUEL SYSTEM</b>				<b>9. FRAME</b>				<b>13. WINDSHIELD WIPERS</b>
NA			a. Visible leak.	✓			a. Frame Members	NA			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			b. Fuel tank filler cap missing.	✓			b. Tire and Wheel Clearance				
			c. Fuel tank securely attached.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
			<b>5. LIGHTING DEVICES</b>								<b>14. MOTORCOACH SEATS</b>
✓			All lighting devices and reflectors required by Part 393 shall be operable.	✓							Any passenger seat that is not securely fastened to the vehicle structure.
											<b>15. OTHER</b>
											List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.



## ANNUAL VEHICLE INSPECTION REPORT

## VEHICLE HISTORY RECORD

REPORT  
NUMBER

FLEET UNIT NUMBER

3793

DATE 4/26/19

MOTOR CARRIER OPERATOR <b>Ray SALMON TRUCKING LLC</b>		INSPECTOR'S NAME (PRINT OR TYPE) <b>RODNEY FARMER</b>	
ADDRESS <b>P.O. Box 799</b>		THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES	
CITY, STATE, ZIP CODE <b>RANNAULTOWN MD 21133</b>		VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER <b>3H3V532CX9T703010</b>	
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)		INSPECTION AGENCY/LOCATION (OPTIONAL)	

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
<b>1. BRAKE SYSTEM</b>				<b>6. SAFE LOADING</b>				<b>10. TIRES</b>			
✓			a. Service Brakes	✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	✓			a. Tires on any steering axle of a power unit.
✓			b. Parking Brake System	✓			b. Protection against shifting cargo.	✓			b. All other tires.
✓			c. Brake Drums or Rotors	✓			c. Container securement devices on intermodal equipment.	✓			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
✓			d. Brake Hose	✓				✓			
✓			e. Brake Tubing	✓				✓			
NA			f. Low Pressure Warning Device	✓				✓			
NA			g. Tractor Protection Valve	✓				✓			
NA			h. Air Compressor	✓				✓			
NA			i. Electric Brakes	✓				✓			
NA			j. Hydraulic Brakes	✓				✓			
NA			k. Vacuum Systems	✓				✓			
✓			l. Antilock Brake System	NA				✓			
✓			m. Automatic Brake Adjusters	✓				✓			
<b>2. COUPLING DEVICES</b>				<b>7. STEERING MECHANISM</b>				<b>11. WHEELS AND RIMS</b>			
✓	NA		a. Fifth Wheels	✓			a. Steering Wheel Free Play	✓			a. Lock or Side Ring
✓	NA		b. Pintle Hooks	✓			b. Steering Column	✓			b. Wheels and Rims
✓	NA		c. Drawbar/Towbar Eye	✓			c. Front Axle Beam and All Steering Components Other Than Steering Column	✓			c. Fasteners
✓	NA		d. Drawbar/Towbar Tongue	✓			d. Steering Gear Box	✓			d. Welds
✓	NA		e. Safety Devices	✓			e. Pitman Arm	✓			
✓	NA		f. Saddle-Mounts	✓			f. Power Steering	✓			
<b>3. EXHAUST SYSTEM</b>				<b>8. SUSPENSION</b>				<b>12. WINDSHIELD GLAZING</b>			
NA			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	NA			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
✓			b. Bus exhaust system leaking or discharging in violation of standard.	✓			b. Spring Assembly	✓			
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓			c. Torque, Radius or Tracking Components	✓			
<b>4. FUEL SYSTEM</b>				<b>9. FRAME</b>				<b>13. WINDSHIELD WIPERS</b>			
✓	NA		a. Visible leak.	✓			a. Frame Members	✓			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
✓	NA		b. Fuel tank filler cap missing.	✓			b. Tire and Wheel Clearance	✓			
✓	NA		c. Fuel tank securely attached.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)	✓			
<b>5. LIGHTING DEVICES</b>								<b>14. MOTORCOACH SEATS</b>			
✓			All lighting devices and reflectors required by Part 393 shall be operable.	✓				✓			Any passenger seat that is not securely fastened to the vehicle structure.
								<b>15. OTHER</b>			
								List any other condition(s) which may prevent safe operation of this vehicle.			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ X NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.