

# ANNUAL VEHICLE INSPECTION REPORT

## VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
	3795
DATE 9-23-17	

MOTOR CARRIER OPERATOR <b>Roy Salmon LLC</b>	INSPECTOR'S NAME (PRINT OR TYPE) <b>Rodney Farmer</b>
ADDRESS <b>1</b>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER <b>3H3V532C4HT253033</b>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
<b>1. BRAKE SYSTEM</b>				<b>6. SAFE LOADING</b>				<b>10. TIRES</b>			
/			a. Service Brakes	/			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	/			a. Tires on any steering axle of a power unit.
/			b. Parking Brake System	/			b. Protection against shifting cargo.	/			b. All other tires.
/			c. Brake Drums or Rotors	/			c. Container securement devices on intermodal equipment.	/			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
/			d. Brake Hose	/				/			
/			e. Brake Tubing	/				/			
/			f. Low Pressure Warning Device	/				/			
/			g. Tractor Protection Valve	/				/			
/			h. Air Compressor	/				/			
/			i. Electric Brakes	/				/			
/			j. Hydraulic Brakes	/				/			
/			k. Vacuum Systems	/				/			
/			l. Antilock Brake System	/				/			
/			m. Automatic Brake Adjusters	/				/			
<b>2. COUPLING DEVICES</b>				<b>7. STEERING MECHANISM</b>				<b>11. WHEELS AND RIMS</b>			
/			a. Fifth Wheels	/			a. Steering Wheel Free Play	/			a. Lock or Side Ring
/			b. Pintle Hooks	/			b. Steering Column	/			b. Wheels and Rims
/			c. Drawbar/Towbar Eye	/			c. Front Axle Beam and All Steering Components Other Than Steering Column	/			c. Fasteners
/			d. Drawbar/Towbar Tongue	/			d. Steering Gear Box	/			d. Welds
/			e. Safety Devices	/			e. Pitman Arm	/			
/			f. Saddle-Mounts	/			f. Power Steering	/			
<b>3. EXHAUST SYSTEM</b>				<b>8. SUSPENSION</b>				<b>12. WINDSHIELD GLAZING</b>			
/			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	/			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	/			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
/			b. Bus exhaust system leaking or discharging in violation of standard.	/			b. Spring Assembly	/			
/			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	/			c. Torque, Radius or Tracking Components	/			
<b>4. FUEL SYSTEM</b>				<b>9. FRAME</b>				<b>13. WINDSHIELD WIPERS</b>			
/			a. Visible leak.	/			a. Frame Members	/			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
/			b. Fuel tank filler cap missing.	/			b. Tire and Wheel Clearance	/			
/			c. Fuel tank securely attached.	/			c. Adjustable Axle Assemblies (Sliding Subframes)	/			
<b>5. LIGHTING DEVICES</b>								<b>14. MOTORCOACH SEATS</b>			
/			All lighting devices and reflectors required by Part 393 shall be operable.	/				/			Any passenger seat that is not securely fastened to the vehicle structure.
								<b>15. OTHER</b>			
								List any other condition(s) which may prevent safe operation of this vehicle.			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, ☒ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.