

# ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
55701745	3803
DATE 1/05/2023	

MOTOR CARRIER OPERATOR <b>Roy Salmon Trucking LLC</b>		INSPECTOR'S NAME (PRINT OR TYPE) <b>James Whithman</b>
ADDRESS <b>8333 Pulaski hwy</b>		THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <b>Rosedale MD 21237</b>		VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER <b>3H3V532C2JR097030</b>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)		INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
<b>1. BRAKE SYSTEM</b>			
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
NA			f. Low Pressure Warning Device
NA			g. Tractor Protection Valve
NA			h. Air Compressor
NA			i. Electric Brakes
NA			j. Hydraulic Brakes
NA			k. Vacuum Systems
✓			l. Antilock Brake System
			m. Automatic Brake Adjusters
<b>2. COUPLING DEVICES</b>			
NA			a. Fifth Wheels
NA			b. Pintle Hooks
NA			c. Drawbar/Towbar Eye
NA			d. Drawbar/Towbar Tongue
NA			e. Safety Devices
NA			f. Saddle-Mounts
<b>3. EXHAUST SYSTEM</b>			
NA			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.
NA			b. Bus exhaust system leaking or discharging in violation of standard.
NA			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.
<b>4. FUEL SYSTEM</b>			
NA			a. Visible leak.
			b. Fuel tank filler cap missing.
			c. Fuel tank securely attached.
<b>5. LIGHTING DEVICES</b>			
✓			All lighting devices and reflectors required by Part 393 shall be operable.
<b>6. SAFE LOADING</b>			
✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
✓			b. Protection against shifting cargo.
			c. Container securement devices on intermodal equipment.
<b>7. STEERING MECHANISM</b>			
			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam and All Steering Components Other Than Steering Column
			d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
<b>8. SUSPENSION</b>			
✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
<b>9. FRAME</b>			
			a. Frame Members
			b. Tire and Wheel Clearance
			c. Adjustable Axle Assemblies (Sliding Subframes)
<b>10. TIRES</b>			
✓			a. Tires on any steering axle of a power unit.
✓			b. All other tires.
✓			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
<b>11. WHEELS AND RIMS</b>			
✓			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds
<b>12. WINDSHIELD GLAZING</b>			
NA			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
<b>13. WINDSHIELD WIPERS</b>			
NA			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
<b>14. MOTORCOACH SEATS</b>			
NA			Any passenger seat that is not securely fastened to the vehicle structure.
<b>15. OTHER</b>			
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION. ☒ OK ☒ X NEEDS REPAIR ☒ NA IF ITEMS DO NOT APPLY. ☐ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.