

# ANNUAL VEHICLE INSPECTION REPORT

## VEHICLE HISTORY RECORD

REPORT  
NUMBER

FLEET UNIT NUMBER

935094

DATE

4-2-21

MOTOR CARRIER OPERATOR

ROY SALMON

INSPECTOR'S NAME (PRINT OR TYPE)

Chris Topper

ADDRESS

8333 PULASKI HWY

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YES

867F99 780094

CITY, STATE, ZIP CODE

BALTO. MD 21237

VEHICLE IDENTIFICATION (✓ AND COMPLETE)

☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

3A1KJGLDSXESF54513

VEHICLE TYPE

☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS

☐ (OTHER)

INSPECTION AGENCY/LOCATION (OPTIONAL)

577CH28

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKE SYSTEM</b>				<b>6. SAFE LOADING</b>				<b>10. TIRES</b>
			a. Service Brakes				a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.				a. Tires on any steering axle of a power unit.
			b. Parking Brake System				b. Protection against shifting cargo.				b. All other tires.
			c. Brake Drums or Rotors				c. Container securement devices on intermodal equipment.				c. Installation of speed-restricted tires unless specifically designated by motor carrier.
			d. Brake Hose								
			e. Brake Tubing								
			f. Low Pressure Warning Device								
			g. Tractor Protection Valve								
			h. Air Compressor								
			i. Electric Brakes								
			j. Hydraulic Brakes								
			k. Vacuum Systems								
			l. Antilock Brake System								
			m. Automatic Brake Adjusters								
			<b>2. COUPLING DEVICES</b>				<b>7. STEERING MECHANISM</b>				<b>11. WHEELS AND RIMS</b>
			a. Fifth Wheels				a. Steering Wheel Free Play				a. Lock or Side Ring
			b. Pintle Hooks				b. Steering Column				b. Wheels and Rims
			c. Drawbar/Towbar Eye				c. Front Axle Beam and All Steering Components Other Than Steering Column				c. Fasteners
			d. Drawbar/Towbar Tongue				d. Steering Gear Box				d. Welds
			e. Safety Devices				e. Pitman Arm				
			f. Saddle-Mounts				f. Power Steering				
			<b>3. EXHAUST SYSTEM</b>				g. Ball and Socket Joints				<b>12. WINDSHIELD GLAZING</b>
			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.				h. Tie Rods and Drag Links				Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
			b. Bus exhaust system leaking or discharging in violation of standard.				i. Nuts				
			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.				j. Steering System				
			<b>4. FUEL SYSTEM</b>				<b>8. SUSPENSION</b>				<b>13. WINDSHIELD WIPERS</b>
			a. Visible leak.				a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			b. Fuel tank filler cap missing.				b. Spring Assembly				
			c. Fuel tank securely attached.				c. Torque, Radius or Tracking Components				
			<b>5. LIGHTING DEVICES</b>				<b>9. FRAME</b>				<b>14. MOTORCOACH SEATS</b>
			All lighting devices and reflectors required by Part 393 shall be operable.				a. Frame Members				Any passenger seat that is not securely fastened to the vehicle structure.
							b. Tire and Wheel Clearance				
							c. Adjustable Axle Assemblies (Sliding Subframes)				
											<b>15. OTHER</b>
											List any other condition(s) which may prevent safe operation of this vehicle.
											SPR
											LST

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN